






# HID CPU Firmware Revision History

PRODUCTS	<b>Scenius Profile</b> <b>Scenius Spot</b> <b>Spheriscan</b> <b>Spherilight</b>	<b>Sharpy series</b> <b>Supersharpy</b> <b>Supersharpy<sup>2</sup></b> <b>Myhos</b> <b>Mythos<sup>2</sup></b>	<b>Alpha 1500 series</b> <b>Alpha 800 series</b> <b>Alpha 700 series</b> <b>Shotlight Wash<sup>(*)</sup></b>
----------	--	---	---

## Key

	Grey background	The firmware is <b>not suitable</b> for the fixture.
	Green background with dot	The firmware is the <b>latest one</b> available for the fixture and includes changes from the previous version for the same fixture.
	Green background	The firmware is the latest one available for the fixture but it does <u>not</u> include any changes from the previous version for the same fixture.
	White background with dot	The firmware includes changes from the previous version for the fixture but newer versions are currently available for the same fixture.
	White background	The firmware is suitable for the fixture but it does <u>not</u> include any changes from the previous version and newer versions are available for the same fixture.

(\*) Fixtures identified by this symbol were discontinued

# HID CPU Firmware Revision History

01/2017

Page 2 of 21

ELECTRONIC BOARD	TYPE <b>CP0100</b>	DESCRIPTION CPU electronic board											
	CP PART NUMBER <b>699188</b> , for Alpha 1500 series, Spotlight Wash, Scenius series; <b>699189</b> , for Alpha 700-800 series, Sharpy series, Supersharpy, Mythos; <b>SCH03E/001</b> , for Spheriscan, Spherilight;												
	IDENTIFICATION ON FIXTURE'S DISPLAY (INFORMATION ➔SYSTEM VERSION MENU) <div><div><div><div>System version</div><table><tr><th>Board</th><th>Revis.</th><th>Hw.rv</th></tr><tr><td>CPU brd</td><td>2.16.4</td><td>0.2</td></tr><tr><td>com.dev</td><td>0.14</td><td></td></tr><tr><td>0: PT-3f</td><td>0.10</td><td>0.1</td></tr></table></div><div><div></div><div></div></div></div></div>		Board	Revis.	Hw.rv	CPU brd	2.16.4	0.2	com.dev	0.14		0: PT-3f	0.10
Board	Revis.	Hw.rv											
CPU brd	2.16.4	0.2											
com.dev	0.14												
0: PT-3f	0.10	0.1											

Filename	Nameroot	Revision	Extension
	<b>HID_FW_</b>	<b>N.N.NNN</b>	<b>.img</b>

Upload system	Fixture-to-Fixture	Firmware <b>Up</b> Loader (C61206 kit)	Web Server
---------------	--------------------	---	------------

[illegible]

REVISION DATE	DESCRIPTION	Alpha 700	Alpha 800	Alpha 1500	Sharp	Sharp Wash 330	SharpWash330 PC	Supersharpy Supersharpy <sup>2</sup>	Mythos <sup>2</sup> – Mythos <sup>2</sup>	Speriscan	Spherilight	Scenius Spot	Scenius Profile
<b>2.16.002</b> 05 December 2016	<p>Identification in the fixture's user menu (Board) <b>CPU brd (Rev.) 2.16.2</b></p> <ul style="list-style-type: none"> <li>• <b>Mythos / Supersharpy</b> <ul style="list-style-type: none"> <li>○ Added the new ventilation management according with the new <b>PHILIPS LAMP 20RB (LAM00K)</b>.</li> </ul> </li> </ul> <p><b>The lamp PHILIPS 20R is not supported with the actual firmware version</b></p> <ul style="list-style-type: none"> <li>• <b>Mythos<sup>2</sup> / Supersharpy<sup>2</sup></b> <ul style="list-style-type: none"> <li>○ Improved the cooling system when the Animation disk is inserted.</li> <li>○ Solved minor bugs.</li> </ul> </li> </ul> <p><b>This is the official firmware release for Mythos<sup>2</sup> and Supersharpy<sup>2</sup>.</b></p> <p><b>WARNING ! It is absolutely required to update the firmware 2.16.002 if "Osram lamp" and "Philips 20RB" lamps are installed.</b></p>							●	●				



[illegible]

[illegible]

[illegible]



[illegible]

<b>REVISION DATE</b>	<b>DESCRIPTION</b>	Alpha 700	Alpha 800	Alpha 1500	Sharp <sup>y</sup>	Sharpy Wash 330	SharpyWash330 PC	Supersharp <sup>y</sup>	Mythos	Speriscan	Spherilight	Scenius Spot
<b>2.12.007</b> <i>Mar, 1<sup>st</sup> 16</i>	Identification in the fixture's user menu (Board) <b>CPU brd (Rev.) 2.12.7</b> • In <b>Mythos:</b> ○ Retrieving multiple times the ballast driver version from the dedicated menu voice does not cause the lamp do douse anymore;								●			
<b>2.12.006</b> <i>Feb, 29<sup>th</sup> 16</i>	Identification in the fixture's user menu (Board) <b>CPU brd (Rev.) 2.12.6</b> • In <b>Spheriscan:</b> ○ The mirror's pan is now homing as expected after the continuous rotation channel has been used in the 1-126 range;									●		
<b>2.12.005</b> <i>Feb, 29<sup>th</sup> 16</i>	Identification in the fixture's user menu (Board) <b>CPU brd (Rev.) 2.12.5</b> • In <b>Mythos:</b> ○ CMY homing accuracy improved after strenuous movement sessions. • In <b>all units except Spheriscan:</b> ○ "Dome's Leds Cal" voice is not listed anymore in the Advanced menu	●	●	●	●	●	●	●	●		●	●